

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/29/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole\_ID: S05AA\_014MH

Test ID: D1032-013006

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Manhole	S05AA_014MH
198.5	10		Tap Factory Active	From 1212 Wildwood
198.5			Dye Test Visible	@ TFA - cleanout
204.1000061	03		Hole Void Visible	
204.1000061			Dye Test Visible	@ HVV - downspout
204.1000061			End of Survey	
204.1489410			Manhole	S05AA_V01MH